Scope of	Work for Property Lo	cated	at:			<u>3130</u> -	-32 North	11th St	<u>reet</u>		
	Property is: Single Fa	mily		Dup	lex	V	Other \square			_	
Date:	9/24/2015										
take no respo	minimum requirement to meet lonsibility for problems discovered by private lenders, insurance co	after the	inspe	ection	date	, or for or	nissions throu	gh error or c	oversight. Th		
Exterior	Condition Report										
Location Site	Required Work Landscaping	n/a	V	Yes		Note/0 Self He	Comments /p				\$ Cost
	Steps/Handrails	n/a	√	Yes							\$
	Service walks	n/a	V	Yes							\$
	Fencing	n/a		Yes	✓						\$ 800.00
	Parking	n/a	✓	Yes							\$
	Retaining walls	n/a	V	Yes							\$
	Other	n/a		Yes							\$
	Other	n/a		Yes							\$
Garage	Singles: repair	n/a		Yes							\$
	Shingles: Roof over existing	n/a		Yes							\$
	Shingles:Tear off & re-roof	n/a		Yes							\$
	Gutters/downspouts	n/a		Yes							\$
	Flashing	n/a		Yes							\$
	Eaves	n/a		Yes							\$
	Siding	n/a		Yes							\$
	Doors	n/a		Yes							\$
	Windows	n/a		Yes							\$
	Slab	n/a		Yes							\$
	Paint	n/a		Yes							\$
	Electrical	n/a		Yes							\$
	Other	n/a		Yes							\$
Porches	Roof	n/a	√	Yes							\$
	Deck-upper	n/a	V	Yes							\$
	Decklower	n/a		Yes	✓	repair,	install handra	ail & paint			\$ 1,600.00
	Steps/handrails	n/a	V	Yes							\$
	Ceiling	n/a	V	Yes							\$
	Guardrails	n/a	V	Yes							\$
	Structural	n/a	4	Yes							\$
	Paint	n/a	V	Yes							\$

Other n/a Yes

\$

House

Chimney	n/a ☑ Yes 🗌	\$
Shingles: repair	n/a ☑ Yes 🗌	\$
Shingles: Roof over existing	n/a ☑ Yes 🗌	\$
Shingles:Tear off & re-roof	n/a ☑ Yes 🗌	\$
Gutters/downspouts	n/a ☑ Yes 🗌	\$
Flashing	n/a ☑ Yes 🗌	\$
Eaves	n/a ☑ Yes 🗌	\$
Siding	n/a ☐ Yes ☑	\$ 500.00
Storm Doors	n/a ☑ Yes 🗌	\$
Prime ("main") Doors	n/a ☑ Yes 🗌	\$
Storm Windows	n/a ☐ Yes ☑	\$ 600.00
Prime ("main") Windows	n/a ☐ Yes ✓	\$ 1,860.00
Paint	n/a ☑ Yes 🗌	\$
Foundation	n/a ☑ Yes 🗌	\$
Electrical	n/a ☑ Yes 🗌	\$
Other	n/a ☐ Yes ☐	\$
Other	n/a ☐ Yes ☐	\$
Other	n/a ☐ Yes ☐	\$
Other	n/a 🗌 Yes 🗌	\$

Exterior: Estimated Cost:* \$ 5,360.00

^{*}average contracted cost. Actual costs may vary. Self help will reduce the amount.

Interior Co	onaition Report						
	Unit: Entire unit (single family)					Lower unit of duplex	
Mechanical	Upper unit of duplex Required Work					Other	
Heating	required Work						
	Repair/replace boiler	n/a	V	Yes			\$
	Repair radiation	n/a	V	Yes			\$
	Repair/replace furnace	n/a	V	Yes			\$
	Repair ductwork	n/a	V	Yes			\$
	Replace thermostat	n/a	V	Yes			\$
	Other	n/a		Yes	~	exhaust vent piping (includes for water heaters)	\$ 275.00
Floorie el	Tune boiler/furn. insp ht exchange	e n/a		Yes	V		\$ 400.00
Electrical	Repair/replace receptacles	n/a	V	Yes			\$
	Repair/replace switches	n/a	V	Yes			\$
	Repair/replace fixtures	n/a	V	Yes			\$
	Install outlets and circuits	n/a	V	Yes			\$
	Install outlets and circuits	n/a	V	Yes			\$
	Install outlets and circuits	n/a	✓	Yes			\$
	Install outlets and circuits	n/a	V	Yes			\$
	Upgrade service	n/a	V	Yes			\$
	Other	n/a		Yes	V	wiring @ furnace	\$ 200.00
	Other	n/a		Yes	✓	permit	\$ 85.00
Plumbing	Repair/replace kitchen sink	n/a	✓	Yes			\$
	Repair/replace kitchen sink fauce	₁n/a	V	Yes			\$
	Repair/replace tub	n/a	V	Yes			\$
	Repair/replace tub faucet	n/a	V	Yes			\$
	Repair/replace toilet	n/a	V	Yes			\$
	Repair/replace lavatory	n/a	V	Yes			\$
	Repair/replace lavatory faucet	n/a	V	Yes			\$
	Repair/replace wash tub	n/a	✓	Yes			\$
	Repair/replace wash tub faucet	n/a	- -	Yes			\$
	Unclog piping:	n/a	✓	Yes			\$
	Repair drain/waste/vent piping	n/a		Yes	V	kitchen	\$ 240.00
	Repair water piping	n/a		Yes	✓	in basement	\$ 400.00
	Repair/replace water heater	n/a	✓	Yes			\$
	Other	n/a		Yes	<u> </u>	water heater overflow piping	\$ 125.00

\$

85.00

Other

n/a 🗌 Yes 🗹 permit

n/a ✓ Yes [\$
n/a ☑ Yes []	\$
n/a Yes		\$ 350.00
ches n/a ✓ Yes	Self Help	\$
***** / V	-	•
tive n/a 🗸 Yes		\$
*****	7	•
tive n/a 🗸 Yes		\$
	0-1511-1-	¢ 55.00
::bsmt. n/a	у у негр	\$ 55.00
: 1st flr. n/a 🗌 Yes 🖸	Self Help	\$ 165.00
: 2nd flr. n/a 🗸 Yes [Self Help	\$
	_	
e n/a ∐ Yes L	to basement	\$ 248.00
n/a ☑ Yes []	\$
n/a ☑ Yes [\$
n/a □ Yes □	1	\$
<u>—</u>	-	·
n/a 📙 Yes L		\$
n/a 🗌 Yes 🛭]	\$
n/a □ Vec □	٦	\$
	n/a	n/a

Interior Co	ondition Report								
	Unit: Entire unit (single family) Upper unit of duplex	□				Lower unit of duplex Other	=		
	Required Work								
Heating	Repair/replace boiler	n/a	V	Yes				\$	
	Repair radiation	n/a	<u> </u>	Yes				\$	
	Repair/replace furnace	n/a	7	Yes				**************************************	
	Repair ductwork	n/a	✓	Yes	<u> </u>		_	\$	
	Replace thermostat	n/a	✓ _	Yes	<u> </u>			\$	
	Repair/replace grilles	n/a	√	Yes				\$	
Electrical	Tune boiler/furn. insp ht exchange	e n/a		Yes	✓			\$	400.00
Liectrical	Repair/replace receptacles	n/a	✓	Yes				\$	
	Repair/replace switches	n/a	V	Yes				 \$	
	Repair/replace fixtures	n/a	√	Yes				\$	
	Install outlets and circuits	n/a	√	Yes				\$	
	Install outlets and circuits	n/a	V	Yes				\$	
	Install outlets and circuits	n/a	V	Yes				\$	
	Install outlets and circuits	n/a	√	Yes				\$	
	Upgrade service	n/a	V	Yes				\$	
	Other	n/a		Yes				\$	
	Other	n/a		Yes				\$	
Plumbing	Repair/replace kitchen sink	n/a	~	Yes				\$	
	Repair/replace kitchen sink fauce	₁n/a	√	Yes				\$	
	Repair/replace tub	n/a	√	Yes				\$	
	Repair/replace tub faucet	n/a	√	Yes				\$	
	Repair/replace toilet	n/a	V	Yes				\$	
	Repair/replace lavatory	n/a	V	Yes				\$	
	Repair/replace lavatory faucet	n/a	V	Yes				\$	
	Repair/replace wash tub	n/a	V	Yes				\$	
	Repair/replace wash tub faucet	n/a	V	Yes				\$	
	Unclog piping:	n/a	V	Yes				\$	
	Repair drain/waste/vent piping	n/a	V	Yes				\$	
	Repair water piping	n/a	V	Yes				 \$	
	Repair/replace water heater	n/a	V	Yes				 \$	
	Other	n/a		Yes				\$	
	Other	n/a		Yes				\$	

Windows								
	Replace broken glass	n/a 🗔] \	es [\$	
	Repair or replace sash	n/a 🗔] \	es [\$	
Doors								
	Repair or replace doors	n/a	<u> </u>	es [√		\$	380.00
	Repair or repl. locks/latches	n/a] `	es [√	Self Help	\$	110.00
Walls/Ceilin	•						_	
	Repair or repl. @ defective	n/a		es [√		\$	450.00
Paint								
	Repair or repl. @ defective	n/a	`	es [√		\$	450.00
Fire Safety								
	Install smoke/CO alarm:bsmt.	n/a [√	<u> </u>	es [Self Help	\$	
	Install smoke/CO alarm: 1st flr.	n/a [√] \	es [Self Help	\$	
	Install smoke/CO alarm: 2nd flr.	n/a Г	۱ ۱	∕es [7	Self Help	\$	165.00
Handrails								
_	Repair/replace defective	n/a 🗔	<u>'</u>	es [Self Help	\$	
Stairs	Repair defective	n/a √		∕es [_		\$	
Floors	Repail delective	n/a [√	1	165			Ψ	
	Repair defective	n/a) \	es [✓		\$	1,200.00
Other								
		n/a	<u></u>	es [✓	NOTE: No Attic Access	\$	
		n/a] \	es [\$	
		n/a] \	es [\$	
	-	n/a] \	es [\$	
						Interior: Estimated Cost:	\$	5,783.00
						Total Exterior and Interior Cost:*	\$	11,143.00
						*average contracted cost. Actual costs may vary. Self help will redu	ce the amount.	

Inspected by: Tom Frank Date: 9/23/15

Self Help

Work listed as "self help" means the cost estimate includes only the cost of the materials, not labor or equipment.

Important Information Regarding Permits

All plumbing, heating, electrical, and structural repairs require permits before work can start. Permits are also required for other work such as new siding, new drywall, new doors. Permits are obtained at the Development Center located on the first floor of 809 N. Broadway.

Licensed contractors must do the above work, although owner occupants may be eligible to do maintenance work and structural/carpentry repairs.

Owner occupants may be eligible to do plumbing work on the unit they live in, but check with the plumbing inspector first.

 $\label{eq:continuous} Generally, \ minor \ carpentry \ repairs, \ plaster \ patching, \ and \ painting \ do \ not \ require \ permits.$

Anyone disturbing painted surfaces must assume they contain lead paint if the home was built before 1978. Contractors must be licensed to do lead abatement and must obtain a permit. Permits are obtained from the Health Department, located on the first floor of 841 N. Broadway.